

SUBJECT: Radial leaded Film Capacitor **ECQ-U2A(G) / ECQ-E2W(C)**
BULLETIN #: DCN.PG42.03.07.09 Date: March 6, 2009 Page 1 of 1

LAST TIME BUY: April 30, 2009

LAST TIME SHIPMENT: June 30, 2009

SUGGESTED REPLACEMENT: Please see below

DETAILS:

The series affected

ECQ-U2A(G) Metallized Polyester Film Capacitor

ECQ-E2W(C) Noise Suppression Film Capacitor

The recommended replacements are categorized by voltage

* Please note that these are not direct replacements.

ECQ-U2A(G) → ECQ-U(L) / ECQ-U3A(G)

ECQ-E2W(C) → ECQ-E2W(H)