

SUBJECT: Part number change for particular ESE13 detector switch.

BULLETIN #: ECN. PG45.03.21.06-1

Date: March 21, 2006

Page 1 of 1

EFFECTIVE DATE: March 21, 2006

LAST ORDER DATE: April 30, 2006

LAST SHIPMENT DATE: May 31, 2006

REASON FOR CHANGE:

In order to standardize our part number system, we are changing the part number ESE-13H01 to ESE-13H01A, where 'A' denotes positioning and terminal type (without boss, J-bent). The two part numbers are physically identical.

AFFECTED PART NUMBERS: ESE-13H01

REPLACEMENT: ESE-13H01A

PRODUCT DATASHEET:

<http://panasonic.com/industrial/components/pdf/ATB0000CE9.pdf>